



# Your Inspection Report

1306 Winding Trail  
Mississauga, ON

**PREPARED FOR:**

KIM KEHOE  
LISTING AGENT

**INSPECTION DATE:**

Tuesday, June 13, 2017

**PREPARED BY:**

Scott Aitken

Aitken Home Inspections  
49 Riverdale Ave  
Toronto, ON m4k1c2

416 407-4663  
scottaitken@live.ca

June 13, 2017

Dear Kim Kehoe and Listing Agent,

RE: Report No. 2224  
1306 Winding Trail  
Mississauga, ON

Thanks very much for choosing us to perform your home inspection. The inspection itself and the attached report comply with the requirements of the Standards of Practice of our national Association. This document defines the scope of a home inspection.

Clients sometimes assume that a home inspection will include many things that are beyond the scope. We encourage you to read the Standards of Practice so that you clearly understand what things are included in the home inspection and report.

The report has been prepared for the exclusive use of our client. No use by third parties is intended. We will not be responsible to any parties for the contents of the report, other than the party named herein .

The report is effectively a snapshot of the house, recording the conditions on a given date and time. Home inspectors cannot predict future behavior, and as such, we cannot be responsible for things that occur after the inspection. If conditions change, we are available to revisit the property and update our report.

The report itself is copyrighted, and may not be used in whole or in part without our express written permission.

Again, thanks very much for choosing us to perform your home inspection.

Sincerely,

Scott Aitken  
on behalf of  
Aitken Home Inspections

Aitken Home Inspections  
49 Riverdale Ave  
Toronto, ON m4k1c2  
416 407-4663

scottaitken@live.ca

# AGREEMENT

Report No. 2224

1306 Winding Trail, Mississauga, ON June 13, 2017

## PARTIES TO THE AGREEMENT

### Company

Aitken Home Inspections  
49 Riverdale Ave  
Toronto, ON m4k1c2

### Client

Kim Kehoe

### Client

Listing Agent

This is an agreement between Kim Kehoe, Listing Agent and Aitken Home Inspections.

**THIS CONTRACT LIMITS THE LIABILITY OF THE HOME INSPECTION COMPANY.  
PLEASE READ CAREFULLY BEFORE SIGNING.**

In addition to the limitations in the Standards of Practice, the Inspection of this property is subject to the Limitations and Conditions set out in this Agreement. The Inspection is performed in accordance with the Standards of Practice of our national association.

## LIMITATIONS AND CONDITIONS OF THE HOME INSPECTION

There are limitations to the scope of this Inspection. It provides a general overview of the more obvious repairs that may be needed. It is not intended to be an exhaustive list. The ultimate decision of what to repair or replace is yours. One homeowner may decide that certain conditions require repair or replacement, while another will not.

### 1) THE INSPECTION IS NOT TECHNICALLY EXHAUSTIVE.

The Home Inspection provides you with a basic overview of the condition of the property. Because your Home Inspector has only a limited amount of time to go through the property, the Inspection is not technically exhaustive.

Some conditions noted, such as foundation cracks or other signs of settling in a house, may either be cosmetic or may indicate a potential problem that is beyond the scope of the Home Inspection.

If you are concerned about any conditions noted in the Home Inspection Report, we strongly recommend that you consult a qualified Licensed Contractor or Consulting Engineer. These professionals can provide a more detailed analysis of any conditions noted in the Report at an additional cost

### 2) THE INSPECTION IS AN OPINION OF THE PRESENT CONDITION OF THE VISIBLE COMPONENTS.

The Home Inspector's Report is an opinion of the present condition of the property. It is based on a visual examination of the readily accessible features of the building.

A Home Inspection does not include identifying defects that are hidden behind walls, floors or ceilings. This includes wiring, heating, cooling, structure, plumbing and insulation that are hidden or inaccessible.

Some intermittent problems may not be obvious on a Home Inspection because they only happen under certain circumstances. As an example, your Home Inspector may not discover leaks that occur only during certain weather conditions or when a specific tap or appliance is being used in everyday life.

Home Inspectors will not find conditions that may only be visible when storage or furniture is moved. They do not

# AGREEMENT

Report No. 2224

1306 Winding Trail, Mississauga, ON June 13, 2017

remove wall coverings (including wallpaper) or lift flooring (including carpet) or move storage to look underneath or behind.

### 3) THE INSPECTION DOES NOT INCLUDE HAZARDOUS MATERIALS.

This includes building materials that are now suspected of posing a risk to health such as phenol-formaldehyde and urea-formaldehyde based insulation, fiberglass insulation and vermiculite insulation. The Inspector does not identify asbestos roofing, siding, wall, ceiling or floor finishes, insulation or fireproofing. We do not look for lead or other toxic metals in such things as pipes, paint or window coverings.

The Inspection does not deal with environmental hazards such as the past use of insecticides, fungicides, herbicides or pesticides. The Home Inspector does not look for, or comment on, the past use of chemical termite treatments in or around the property.

### 4) WE DO NOT COMMENT ON THE QUALITY OF AIR IN A BUILDING.

The Inspector does not try to determine if there are irritants, pollutants, contaminants, or toxic materials in or around the building.

The Inspection does not include spores, fungus, mold or mildew that may be present. You should note that whenever there is water damage noted in the report, there is a possibility that mold or mildew may be present, unseen behind a wall, floor or ceiling.

If anyone in your home suffers from allergies or heightened sensitivity to quality of air, we strongly recommend that you consult a qualified Environmental Consultant who can test for toxic materials, mold and allergens at additional cost.

### 5) WE DON'T LOOK FOR BURIED TANKS.

Your Home Inspector does not look for and is not responsible for fuel oil, septic or gasoline tanks that may be buried on the property. If the building had its heating system converted from oil, there will always be the possibility that a tank may remain buried on the property.

If fuel oil or other storage tanks remain on the property, you may be responsible for their removal and the safe disposal of any contaminated soil. If you suspect there is a buried tank, we strongly recommend that you retain a qualified Environmental Consultant to determine whether this is a potential problem.

### 6) TIME TO INVESTIGATE

We will have no liability for any claim or complaint if conditions have been disturbed, altered, repaired, replaced or otherwise changed before we have had a reasonable period of time to investigate.

### 7) REPORT IS FOR OUR CLIENT ONLY

The inspection report is for the exclusive use of the client named herein. No use of the information by any other party is intended.

# AGREEMENT

1306 Winding Trail, Mississauga, ON June 13, 2017

## 8) CANCELLATION FEE

If the inspection is cancelled within 24 hours of the appointment time, a cancellation fee of 50% of the inspection fee will apply.

## 9) NOT A GUARANTEE, WARRANTY OR INSURANCE POLICY.

The inspection is not a guarantee, warranty or an insurance policy with regard to the fitness of the property.

## 10) LIMIT OF LIABILITY / LIQUIDATED DAMAGES

The liability of the Home Inspector and the Home Inspection Company arising out of this Inspection and Report, for any cause of action whatsoever, whether in contract or in negligence, is limited to a refund of the fees that you have been charged for this inspection.

**I, Kim Kehoe (Signature) \_\_\_\_\_, (Date) \_\_\_\_\_, have read, understood and accepted the terms of this agreement.**

**I, Listing Agent (Signature) \_\_\_\_\_, (Date) \_\_\_\_\_, have read, understood and accepted the terms of this agreement.**

# SUMMARY

1306 Winding Trail, Mississauga, ON June 13, 2017

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

CHIMNEY

FIREPLACES

REFERENCE

**Note:** For the purpose of this report the building is considered to be facing **West**.

Home in very good condition.

This Summary outlines potentially significant issues from a cost or safety standpoint. This section is provided as a courtesy and cannot be considered a substitute for reading the entire report. Please read the complete document.

[Priority Maintenance Items](#)

This concludes the Summary section.

The remainder of the report describes each of the home's systems and also details any recommendations we have for improvements. Limitations that restricted our inspection are included as well.

The suggested time frames for completing recommendations are based on the limited information available during a pre-purchase home inspection. These may have to be adjusted based on the findings of specialists.

[Home Improvement - ballpark costs](#)

# ROOFING

1306 Winding Trail, Mississauga, ON June 13, 2017

- SUMMARY
- ROOFING**
- EXTERIOR
- STRUCTURE
- ELECTRICAL
- HEATING
- COOLING
- INSULATION
- PLUMBING
- INTERIOR
- CHIMNEY
- FIREPLACES
- REFERENCE

## Description

### Sloped roofing material:

- [Asphalt shingles](#)  
Aprox. 3 years old.



1. *Asphalt shingles*

### Flat roofing material:

- [Modified bitumen](#)  
Aprox. 15 years old.



2. *Modified bitumen*

Probability of leakage: • Low

## Limitations

Inspection performed: • By walking on roof

# ROOFING

1306 Winding Trail, Mississauga, ON June 13, 2017

SUMMARY	<b>ROOFING</b>	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR
CHIMNEY	FIREPLACES	REFERENCE							

## Recommendations

### **FLAT ROOFING \ Modified bitumen**

**1. Condition:** • Vulnerable areas.

Remove loose nail, seal opening, and clear downspout.

**Location:** Garage roof

**Task:** Improve

**Time:** Immediate

**Cost:** Minor



**3. Vulnerable areas.**

# EXTERIOR

1306 Winding Trail, Mississauga, ON June 13, 2017

- SUMMARY
- ROOFING
- EXTERIOR**
- STRUCTURE
- ELECTRICAL
- HEATING
- COOLING
- INSULATION
- PLUMBING
- INTERIOR
- CHIMNEY
- FIREPLACES
- REFERENCE

## Description

**Gutter & downspout material:** • [Aluminum](#)  
**Downspout discharge:** • [Below grade](#) • [Above grade](#)  
**Lot slope:** • [Flat](#)  
**Wall surfaces - masonry:** • [Brick](#)  
**Soffit and fascia:** • [Aluminum](#)  
**Driveway:** • Asphalt  
**Walkway:** • Interlocking brick  
**Patio:** • Interlocking brick  
**Garage:** • Attached.

## Limitations

**Inspection limited/prevented by:** • Car/storage in garage

## Recommendations

**PORCHES, DECKS, STEPS, PATIOS AND BALCONIES \ Patios**  
**2. Condition:** • [Trip hazards](#)  
Lift and relay bricks at east patio step to eliminate trip hazard.  
**Implication(s):** Physical injury  
**Location:** East Exterior  
**Task:** Improve  
**Time:** Immediate  
**Cost:** Minor

SUMMARY	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR
CHIMNEY	FIREPLACES	REFERENCE							



4. Trip hazards

### LANDSCAPING \ Driveway

**3. Condition:** • [Unsealed gap at building](#)

Fill void at joint between driveway and garage.

**Implication(s):** Chance of water damage to contents, finishes and/or structure

**Task:** Improve


**Time:** Discretionary

**Cost:** Minor

# EXTERIOR

1306 Winding Trail, Mississauga, ON June 13, 2017

SUMMARY	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR
CHIMNEY	FIREPLACES	REFERENCE							



5. Unsealed gap at building

## **GARAGE \ Vehicle door operators**

4. Condition: • [Extension cord for opener](#)

Add two outlets at garage ceiling for openers.

**Implication(s):** Electric shock

**Location:** Garage


**Task:** Improve

**Cost:** Minor

# EXTERIOR

1306 Winding Trail, Mississauga, ON June 13, 2017

- SUMMARY
- ROOFING
- EXTERIOR**
- STRUCTURE
- ELECTRICAL
- HEATING
- COOLING
- INSULATION
- PLUMBING
- INTERIOR
- CHIMNEY
- FIREPLACES
- REFERENCE



**5. Condition:** • [Sensors inoperative](#)

Electric eye auto reverse inoperative at south door.

**Implication(s):** Physical injury

**Location:** Garage


**Task:** Repair

**Time:** Immediate

**Cost:** Minor

SUMMARY	ROOFING	<b>EXTERIOR</b>	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR
CHIMNEY	FIREPLACES	REFERENCE							

## Check photo-eye



while the door is closing,  
break the photo-eye beam  
(with your foot, for example)  
- the door should stop  
immediately, then auto  
reverse to the open position

## Description

**Configuration:** • [Basement](#)

**Foundation material:** • [Poured concrete](#)

**Floor construction:** • [Joists](#) • Subfloor - plank

**Exterior wall construction:** • [Wood frame / Brick veneer](#)

**Roof and ceiling framing:** • Rafters • [Plywood sheathing](#)

## Limitations

**Attic/roof space:** • Inspected from access hatch

**Percent of foundation not visible:** • 80 %

## Recommendations

### FOUNDATIONS \ Foundation


**6. Condition:** • Typical minor cracks

Typical hairline cracks are not structurally significant, but indicate areas of foundation most vulnerable to water entry. These cracks can be epoxy repaired at aprox. \$500 each if leakage develops. No evidence of leakage at time of inspection.

**Implication(s):** Chance of water entering building

**Location:** Various

**Task:** Monitor



SUMMARY	ROOFING	EXTERIOR	<b>STRUCTURE</b>	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR
CHIMNEY	FIREPLACES	REFERENCE							



6. Typical minor cracks



7. Typical minor cracks



8. Typical minor cracks

## Description

**Service entrance cable and location:** • [Underground - cable material not visible](#)

**Service size:** • [100 Amps \(240 Volts\)](#)

**Main disconnect/service box rating:** • [100 Amps](#)

**Main disconnect/service box type and location:** • [Fuses - basement](#)

**System grounding material and type:** • [Copper - water pipe](#)

**Distribution panel rating:** • [100 Amps](#)

**Distribution panel type and location:** • [Breakers - basement](#)

**Distribution wire material and type:** • [Copper - non-metallic sheathed](#) • [Aluminum - non-metallic sheathed](#)

**Type and number of outlets (receptacles):** • [Grounded - typical](#)

**Circuit interrupters: Ground Fault (GFCI) & Arc Fault (AFCI):** • [GFCI - bathroom](#)

**Smoke detectors:** • [Present](#)

**Carbon monoxide (CO) detectors:** • Present

## Recommendations

### **DISTRIBUTION SYSTEM \ Aluminum**

**7. Condition:** • At least one circuit of aluminum wiring present, could not determine if anti oxidant or appropriate connectors are present on load end.

**Task:** Further evaluation

**Cost:** Minor



9. Aluminum

SUMMARY	ROOFING	EXTERIOR	STRUCTURE	<b>ELECTRICAL</b>	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR
CHIMNEY	FIREPLACES	REFERENCE							

### **DISTRIBUTION SYSTEM \ Outdoor wiring**

#### **8. Condition:** • [Extension cords for exterior outlets](#)

Replace unprotected wiring at garage/exterior.

**Implication(s):** Electric shock | Fire hazard

**Location:** West exterior

**Task:** Replace

**Time:** Immediate

**Cost:** Minor



10. Extension cords for exterior outlets

### **DISTRIBUTION SYSTEM \ Outlets (receptacles)**

#### **9. Condition:** • [GFCI/GFI needed \(Ground Fault Circuit Interrupter\)](#)

Recommend gfci receptacles at all wet locations.

**Implication(s):** Electric shock

**Location:** Various First Floor

**Task:** Provide

**Time:** Discretionary

**Cost:** Minor

SUMMARY	ROOFING	EXTERIOR	STRUCTURE	<b>ELECTRICAL</b>	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR
CHIMNEY	FIREPLACES	REFERENCE							


## Ground fault interrupter

the GFI circuitry within the outlet checks constantly for a difference between the current in the black and white wires

if there is a difference (even as little as 5 milliamps), there is a current leak (possibly through your body) and the GFI shuts down the receptacle and other receptacles downstream

**note:**

if the GFI is in the panel, the entire circuit will be shut down



# HEATING

1306 Winding Trail, Mississauga, ON June 13, 2017

- SUMMARY
- ROOFING
- EXTERIOR
- STRUCTURE
- ELECTRICAL
- HEATING**
- COOLING
- INSULATION
- PLUMBING
- INTERIOR
- CHIMNEY
- FIREPLACES
- REFERENCE

## Description

**System type:** • [Furnace](#)  
**Fuel/energy source:** • [Gas](#)  
**Heat distribution:** • [Ducts and registers](#)  
**Approximate capacity:** • [60,000 BTU/hr](#)  
**Efficiency:** • [High-efficiency](#)  
**Approximate age:** • [16 years](#)  
**Main fuel shut off at:** • Meter  
**Failure probability:** • [Medium](#)  
**Chimney/vent:** • High temperature plastic • Sidewall venting  
**Combustion air source:** • Outside - sealed combustion

## Limitations

**Warm weather:** • Prevented testing in heating mode

## Recommendations

### RECOMMENDATIONS \ Overview

**10. Condition:** • No heating recommendations are offered as a result of this inspection.

# COOLING & HEAT PUMP

1306 Winding Trail, Mississauga, ON June 13, 2017

SUMMARY	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR
CHIMNEY	FIREPLACES	REFERENCE							

## Description

- Air conditioning type: • [Air cooled](#)
- Cooling capacity: • [24,000 BTU/hr](#)
- Compressor approximate age: • 13 years
- Failure probability: • [Medium](#)

## Recommendations

### AIR CONDITIONING \ Compressor

11. Condition: • [Missing electrical shutoff](#)


Implication(s): Difficult to service

Location: Exterior Wall

Task: Provide

Time: When necessary

Cost: \$400



# INSULATION AND VENTILATION

1306 Winding Trail, Mississauga, ON June 13, 2017

- SUMMARY
- ROOFING
- EXTERIOR
- STRUCTURE
- ELECTRICAL
- HEATING
- COOLING
- INSULATION**
- PLUMBING
- INTERIOR
- CHIMNEY
- FIREPLACES
- REFERENCE

## Description

Attic/roof insulation material: • [Glass fiber](#)  
Attic/roof insulation amount/value: • [R-24](#)  
Attic/roof air/vapor barrier: • [Plastic](#)  
Attic/roof ventilation: • [Roof and soffit vents](#)  
Wall insulation material: • [Glass fiber](#)  
Wall insulation amount/value: • [R-12](#) • Spot checked only  
Foundation wall insulation material: • [Mineral wool](#)  
Foundation wall insulation amount/value: • 0-12

## Limitations

Attic inspection performed: • From access hatch

## Recommendations

**RECOMMENDATIONS \ Overview**  
12. **Condition:** • Increased insulation is an improvement and not an essential repair.

1306 Winding Trail, Mississauga, ON June 13, 2017

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

CHIMNEY

FIREPLACES

REFERENCE

## Description

**Water supply source:** • Public

**Service piping into building:** • [Copper](#)

**Supply piping in building:** • [Copper](#) • PEX (cross-linked Polyethylene)

**Main water shut off valve at the:** • Furnace room

**Water flow and pressure:** • [Functional](#)

**Water heater type:** • [Conventional](#) • Rental

**Water heater fuel/energy source:** • [Gas](#)

**Tank capacity:** • 227 liters

**Water heater approximate age:** • 15 years

**Water heater failure probability:** • [Medium](#)

**Waste and vent piping in building:** • [ABS plastic](#) • [Copper](#)

**Floor drain location:** • Near water heater

**Backwater valve:** • Not present

## Limitations

**Items excluded from a building inspection:** • Concealed plumbing

## Recommendations

### RECOMMENDATIONS \ Overview

**13. Condition:** • No plumbing recommendations are offered as a result of this inspection.

All fixtures in good working order.

# INTERIOR

1306 Winding Trail, Mississauga, ON June 13, 2017

- SUMMARY
- ROOFING
- EXTERIOR
- STRUCTURE
- ELECTRICAL
- HEATING
- COOLING
- INSULATION
- PLUMBING
- INTERIOR
- CHIMNEY
- FIREPLACES
- REFERENCE

## Description

**Major floor finishes:** • [Hardwood](#) • [Laminate](#) • [Ceramic](#)  
**Major wall finishes:** • [Plaster/drywall](#) • [Paneling](#)  
**Major ceiling finishes:** • [Plaster/drywall](#) • [Suspended tile](#)  
**Windows:** • [Fixed](#) • [Sliders](#)  
**Glazing:** • [Double](#)  
**Exterior doors - type/material:** • Hinged • [Sliding glass](#) • [Metal](#)  
**Evidence of basement leakage:** • None

## Limitations

**Not included as part of a building inspection:** • Appliances  
**Percent of foundation not visible:** • 80 %

## Recommendations

### RECOMMENDATIONS \ Overview

**14. Condition:** • No interior recommendations are offered as a result of this inspection.

# CHIMNEY

1306 Winding Trail, Mississauga, ON June 13, 2017

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

CHIMNEY

FIREPLACES

REFERENCE

## Description

### Masonry\Shell material:

- Brick



11.

### Masonry\Liner type:

- Clay  
For wood burning fireplace.
- Metal  
For water heater.

# FIREPLACES

1306 Winding Trail, Mississauga, ON June 13, 2017

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

CHIMNEY

**FIREPLACES**

REFERENCE

## Description

**General:** • Wood burning masonry fireplace.



12. Wood burning masonry fireplace.

## Recommendations

### General

15. • Fireplace in good condition, no recommendations.

**END OF REPORT**

- SUMMARY
- ROOFING
- EXTERIOR
- STRUCTURE
- ELECTRICAL
- HEATING
- COOLING
- INSULATION
- PLUMBING
- INTERIOR
- CHIMNEY
- FIREPLACES
- REFERENCE**

The links below connect you to a series of documents that will help you understand your home and how it works. These are in addition to links attached to specific items in the report.

Click on any link to read about that system.

» 01. ROOFING, FLASHINGS AND CHIMNEYS

» 02. EXTERIOR

» 03. STRUCTURE

» 04. ELECTRICAL

» 05. HEATING

» 06. COOLING/HEAT PUMPS

» 07. INSULATION

» 08. PLUMBING

» 09. INTERIOR

» 10. APPLIANCES

» 11. LIFE CYCLES AND COSTS

» 12. SUPPLEMENTARY

Asbestos

Radon

Urea Formaldehyde Foam Insulation (UFFI)

Lead

Carbon Monoxide

Mold

Household Pests

Termites and Carpenter Ants

» 13. HOME SET-UP AND MAINTENANCE

» 14. MORE ABOUT HOME INSPECTIONS

