



Your Inspection Report

174 Yarmouth Road
Toronto, ON M4R 1X7

PREPARED FOR:

KIM KEHOE
LISTING AGENT

INSPECTION DATE:

Thursday, October 18, 2018

PREPARED BY:

Scott Aitken

Aitken Home Inspections
49 Riverdale Ave
TORONTO, ON M4K 1C2

4164074663
scottaitken@live.ca

October 18, 2018

Dear Kim Kehoe and Listing Agent,

RE: Report No. 2622
174 Yarmouth Road
Toronto, ON
M4R 1X7

Thanks very much for choosing us to perform your home inspection. The inspection itself and the attached report comply with the requirements of the Standards of Practice of our national Association. This document defines the scope of a home inspection.

Clients sometimes assume that a home inspection will include many things that are beyond the scope. We encourage you to read the Standards of Practice so that you clearly understand what things are included in the home inspection and report.

The report has been prepared for the exclusive use of our client. No use by third parties is intended. We will not be responsible to any parties for the contents of the report, other than the party named herein .

The report is effectively a snapshot of the house, recording the conditions on a given date and time. Home inspectors cannot predict future behavior, and as such, we cannot be responsible for things that occur after the inspection. If conditions change, we are available to revisit the property and update our report.

The report itself is copyrighted, and may not be used in whole or in part without our express written permission.

Again, thanks very much for choosing us to perform your home inspection.

Sincerely,

Scott Aitken
on behalf of
Aitken Home Inspections

Aitken Home Inspections
49 Riverdale Ave
TORONTO, ON M4K 1C2
4164074663

scottaitken@live.ca

AGREEMENT

Report No. 2622

174 Yarmouth Road, Toronto, ON October 18, 2018

PARTIES TO THE AGREEMENT

Company

Aitken Home Inspections
49 Riverdale Ave
TORONTO, ON M4K 1C2

Client

Kim Kehoe

Client

Listing Agent

This is an agreement between Kim Kehoe, Listing Agent and Aitken Home Inspections.

**THIS CONTRACT LIMITS THE LIABILITY OF THE HOME INSPECTION COMPANY.
PLEASE READ CAREFULLY BEFORE SIGNING.**

In addition to the limitations in the Standards of Practice, the Inspection of this property is subject to the Limitations and Conditions set out in this Agreement. The Inspection is performed in accordance with the Standards of Practice of our national association.

LIMITATIONS AND CONDITIONS OF THE HOME INSPECTION

There are limitations to the scope of this Inspection. It provides a general overview of the more obvious repairs that may be needed. It is not intended to be an exhaustive list. The ultimate decision of what to repair or replace is yours. One homeowner may decide that certain conditions require repair or replacement, while another will not.

1) THE INSPECTION IS NOT TECHNICALLY EXHAUSTIVE.

The Home Inspection provides you with a basic overview of the condition of the property. Because your Home Inspector has only a limited amount of time to go through the property, the Inspection is not technically exhaustive.

Some conditions noted, such as foundation cracks or other signs of settling in a house, may either be cosmetic or may indicate a potential problem that is beyond the scope of the Home Inspection.

If you are concerned about any conditions noted in the Home Inspection Report, we strongly recommend that you consult a qualified Licensed Contractor or Consulting Engineer. These professionals can provide a more detailed analysis of any conditions noted in the Report at an additional cost

2) THE INSPECTION IS AN OPINION OF THE PRESENT CONDITION OF THE VISIBLE COMPONENTS.

The Home Inspector's Report is an opinion of the present condition of the property. It is based on a visual examination of the readily accessible features of the building.

A Home Inspection does not include identifying defects that are hidden behind walls, floors or ceilings. This includes wiring, heating, cooling, structure, plumbing and insulation that are hidden or inaccessible.

Some intermittent problems may not be obvious on a Home Inspection because they only happen under certain circumstances. As an example, your Home Inspector may not discover leaks that occur only during certain weather conditions or when a specific tap or appliance is being used in everyday life.

Home Inspectors will not find conditions that may only be visible when storage or furniture is moved. They do not

AGREEMENT

Report No. 2622

174 Yarmouth Road, Toronto, ON October 18, 2018

remove wall coverings (including wallpaper) or lift flooring (including carpet) or move storage to look underneath or behind.

3) THE INSPECTION DOES NOT INCLUDE HAZARDOUS MATERIALS.

This includes building materials that are now suspected of posing a risk to health such as phenol-formaldehyde and urea-formaldehyde based insulation, fiberglass insulation and vermiculite insulation. The Inspector does not identify asbestos roofing, siding, wall, ceiling or floor finishes, insulation or fireproofing. We do not look for lead or other toxic metals in such things as pipes, paint or window coverings.

The Inspection does not deal with environmental hazards such as the past use of insecticides, fungicides, herbicides or pesticides. The Home Inspector does not look for, or comment on, the past use of chemical termite treatments in or around the property.

4) WE DO NOT COMMENT ON THE QUALITY OF AIR IN A BUILDING.

The Inspector does not try to determine if there are irritants, pollutants, contaminants, or toxic materials in or around the building.

The Inspection does not include spores, fungus, mold or mildew that may be present. You should note that whenever there is water damage noted in the report, there is a possibility that mold or mildew may be present, unseen behind a wall, floor or ceiling.

If anyone in your home suffers from allergies or heightened sensitivity to quality of air, we strongly recommend that you consult a qualified Environmental Consultant who can test for toxic materials, mold and allergens at additional cost.

5) WE DON'T LOOK FOR BURIED TANKS.

Your Home Inspector does not look for and is not responsible for fuel oil, septic or gasoline tanks that may be buried on the property. If the building had its heating system converted from oil, there will always be the possibility that a tank may remain buried on the property.

If fuel oil or other storage tanks remain on the property, you may be responsible for their removal and the safe disposal of any contaminated soil. If you suspect there is a buried tank, we strongly recommend that you retain a qualified Environmental Consultant to determine whether this is a potential problem.

6) TIME TO INVESTIGATE

We will have no liability for any claim or complaint if conditions have been disturbed, altered, repaired, replaced or otherwise changed before we have had a reasonable period of time to investigate.

7) REPORT IS FOR OUR CLIENT ONLY

The inspection report is for the exclusive use of the client named herein. No use of the information by any other party is intended.

AGREEMENT

174 Yarmouth Road, Toronto, ON October 18, 2018

8) CANCELLATION FEE

If the inspection is cancelled within 24 hours of the appointment time, a cancellation fee of 50% of the inspection fee will apply.

9) NOT A GUARANTEE, WARRANTY OR INSURANCE POLICY.

The inspection is not a guarantee, warranty or an insurance policy with regard to the fitness of the property.

10) LIMIT OF LIABILITY / LIQUIDATED DAMAGES

The liability of the Home Inspector and the Home Inspection Company arising out of this Inspection and Report, for any cause of action whatsoever, whether in contract or in negligence, is limited to a refund of the fees that you have been charged for this inspection.

I, Kim Kehoe (Signature) _____, (Date) _____, have read, understood and accepted the terms of this agreement.

I, Listing Agent (Signature) _____, (Date) _____, have read, understood and accepted the terms of this agreement.

SUMMARY

Report No. 2622

174 Yarmouth Road, Toronto, ON October 18, 2018

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

REFERENCE

Note: For the purpose of this report the building is considered to be facing **South**.

This Summary outlines potentially significant issues from a cost or safety standpoint. This section is provided as a courtesy and cannot be considered a substitute for reading the entire report. Please read the complete document.

[Priority Maintenance Items](#)

Roofing

SLOPED ROOFING \ Asphalt shingles

Condition: • [Old, worn out](#)

Strip and reshingle sloped areas. Flat roof is newer and in good condition.

Implication(s): Chance of water damage to contents, finishes and/or structure

Task: Replace

Time: Weather permitting

Cost: \$5,000

This concludes the Summary section.

The remainder of the report describes each of the home's systems and also details any recommendations we have for improvements. Limitations that restricted our inspection are included as well.

The suggested time frames for completing recommendations are based on the limited information available during a pre-purchase home inspection. These may have to be adjusted based on the findings of specialists.

[Home Improvement - ballpark costs](#)

ROOFING

Report No. 2622

174 Yarmouth Road, Toronto, ON October 18, 2018

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

REFERENCE

Description

Sloped roofing material:

- [Asphalt shingles](#)



1. *Asphalt shingles*

Flat roofing material:

- [Modified bitumen membrane](#)

ROOFING

174 Yarmouth Road, Toronto, ON October 18, 2018

- SUMMARY
 - ROOFING**
 - EXTERIOR
 - STRUCTURE
 - ELECTRICAL
 - HEATING
 - COOLING
 - INSULATION
 - PLUMBING
 - INTERIOR
- REFERENCE



2. Modified bitumen membrane

Probability of leakage: • High

Limitations

Inspection performed: • From roof edge

Recommendations

SLOPED ROOFING \ Asphalt shingles

1. Condition: • [Old, worn out](#)

Strip and reshingle sloped areas. Flat roof is newer and in good condition.

Implication(s): Chance of water damage to contents, finishes and/or structure

Task: Replace

Time: Weather permitting

Cost: \$5,000

ROOFING

174 Yarmouth Road, Toronto, ON October 18, 2018

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

REFERENCE



3. *Old, worn out*

EXTERIOR

174 Yarmouth Road, Toronto, ON October 18, 2018

- SUMMARY
 - ROOFING
 - EXTERIOR**
 - STRUCTURE
 - ELECTRICAL
 - HEATING
 - COOLING
 - INSULATION
 - PLUMBING
 - INTERIOR
- REFERENCE

Description

- Gutter & downspout material:** • [Aluminum](#) • [Galvanized steel](#)
- Downspout discharge:** • [Below grade](#) • [Above grade](#)
- Lot slope:** • [Flat](#)
- Soffit (underside of eaves) and fascia (front edge of eaves):** • [Wood](#) • [Aluminum](#)
- Wall surfaces - masonry:** • [Brick](#)
- Retaining wall:** • [Wood](#) • [Masonry](#) • [Stone](#)
- Walkway:** • Concrete • Wood
- Deck:** • Pressure-treated wood
- Porch:** • Pressure treated wood

Limitations

- Inspection limited/prevented by:** • Inaccessible wall
- No or limited access to:** • Space between buildings

Recommendations

ROOF DRAINAGE \ Downspouts

2. Condition: • [Discharge below grade](#)

Disconnect downspout and route well away from foundation, create drainage slope away foundation at gravel area.


Implication(s): Chance of water damage to contents, finishes and/or structure

Location: Northeast Exterior

Task: Improve

Time: Immediate

Cost: Minor



4. Discharge below grade

WALLS \ Brick, stone and concrete

3. Condition: • Add pest and weather cover to exhaust duct.

Location: East Second Floor

Task: Improve

Time: Immediate

Cost: Minor



5.

4. Condition: • Seal vent at wall

Caulk vent covers at wall.

Location: East Exterior Wall

Task: Improve

Time: Unpredictable

Cost: Minor



6. Seal vent at wall

5. Condition: • [Cracked](#)

Some tuckpointing needed.

Implication(s): Chance of water entering building | Weakened structure | Chance of movement

Location: Various Exterior Wall

Task: Repair

Time: Unpredictable

Cost: \$1,000 - and up



7. Cracked

EXTERIOR GLASS/WINDOWS \ General

6. Condition: • Flashings incomplete.

Some flashing and caulking needed.

Location: East Exterior Wall

Task: Improve

Time: Immediate

Cost: Minor



8. Caulking incomplete.



9. Flashings incomplete.

BASEMENT WALKOUTS \ General

7. Condition: • [Door threshold missing, too low, not watertight](#)

Basement entrance configured so that step at outside of door is at interior floor level. Ideally exterior landing would be created with a step up into basement to limit potential for water entry to basement. Consider door at top of exterior steps.


Implication(s): Chance of water damage to contents, finishes and/or structure

Location: South Exterior Staircase

Task: Improve

Time: Unpredictable

Cost: Depends on approach



10.


LANDSCAPING \ Retaining wall
8. Condition: • [Settling or shifting](#)

North retaining wall cracked but sound.

Implication(s): Weakened structure | Chance of movement

Location: North Exterior

Task: Monitor



11. Settling or shifting

Description

Configuration: • [Basement](#)

Foundation material: • [Stone](#)

Floor construction: • [Joists](#) • Subfloor - plank

Exterior wall construction: • [Masonry](#)

Roof and ceiling framing: • [Rafters/roof joists](#) • [Plank sheathing](#)

Party walls: • [Masonry](#)

Limitations

Attic/roof space: • Inspected from access hatch

Percent of foundation not visible: • 90 %

Recommendations

RECOMMENDATIONS \ Overview

9. Condition: • All visible structural members in good condition.

10. Condition: • No structure recommendations are offered as a result of this inspection.

- SUMMARY
 - ROOFING
 - EXTERIOR
 - STRUCTURE
 - ELECTRICAL**
 - HEATING
 - COOLING
 - INSULATION
 - PLUMBING
 - INTERIOR
- REFERENCE

Description

Service entrance cable and location: • [Overhead copper](#)

Service size: • [100 Amps \(240 Volts\)](#)

Main disconnect/service box rating: • [100 Amps](#)

Main disconnect/service box type and location: • [Breakers - basement](#)

System grounding material and type: • [Copper - water pipe](#)

Distribution panel type and location: • [Breakers - basement](#)

Distribution panel rating: • [100 Amps](#)

Distribution wire material and type: • [Copper - non-metallic sheathed](#)

Type and number of outlets (receptacles): • [Grounded - upgraded](#)

Circuit interrupters: Ground Fault (GFCI) & Arc Fault (AFCI): • [GFCI - bathroom](#) • [GFCI - kitchen](#) • GFCI - laundry room

Smoke detectors: • [Present](#)

Carbon monoxide (CO) detectors: • Present

Recommendations

RECOMMENDATIONS \ Overview

11. Condition: • No electrical recommendations are offered as a result of this inspection.

HEATING

174 Yarmouth Road, Toronto, ON October 18, 2018

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

REFERENCE

Description

System type: • [Furnace](#)

Fuel/energy source: • [Gas](#)

Heat distribution: • [Ducts and registers](#)

Approximate capacity: • [80,000 BTU/hr](#)

Efficiency: • [High-efficiency](#)

Approximate age: • [New](#)

Main fuel shut off at: • Meter

Failure probability: • [Low](#)

Auxiliary heat: • Electric radiant floor heat

Chimney/vent: • High temperature plastic • Sidewall venting

Combustion air source: • Outside

Limitations

Heat loss calculations: • Not done as part of a building inspection

Recommendations

FURNACE \ Filter

12. Condition: • [Dirty](#)

Vendor to replace air filter.

Implication(s): Increased heating costs | Reduced comfort

Task: Replace

Time: Immediate

Cost: Minor

COOLING & HEAT PUMP

174 Yarmouth Road, Toronto, ON October 18, 2018

- SUMMARY
 - ROOFING
 - EXTERIOR
 - STRUCTURE
 - ELECTRICAL
 - HEATING
 - COOLING**
 - INSULATION
 - PLUMBING
 - INTERIOR
- REFERENCE

Description

Air conditioning type: • [Air cooled](#)
Cooling capacity: • [24,000 BTU/hr](#)
Compressor approximate age: • 4 years

Limitations

Inspection limited/prevented by: • Low outdoor temperature

Recommendations

RECOMMENDATIONS \ Overview

13. Condition: • No air conditioning or heat pump recommendations are offered as a result of this inspection.

INSULATION AND VENTILATION

174 Yarmouth Road, Toronto, ON October 18, 2018

- SUMMARY
 - ROOFING
 - EXTERIOR
 - STRUCTURE
 - ELECTRICAL
 - HEATING
 - COOLING
 - INSULATION**
 - PLUMBING
 - INTERIOR
- REFERENCE

Description

Attic/roof insulation material: • [Glass fiber](#) • Sprayed foam
Attic/roof insulation amount/value: • [R-32](#)
Attic/roof ventilation: • [Roof vent](#)
Wall insulation material: • [Glass fiber](#)
Wall insulation amount/value: • [R-12](#) • Spot checked only
Wall air/vapor barrier: • Plastic
Foundation wall insulation material: • [Glass fiber](#)
Foundation wall insulation amount/value: • 0-12
Foundation wall air/vapor barrier: • Plastic


Limitations

Attic inspection performed: • From access hatch

Recommendations

ATTIC/ROOF \ Insulation
14. Condition: • [Gaps or voids](#)
Implication(s): Increased heating and cooling costs | Reduced comfort
Location: Attic
Task: Improve
Time: Discretionary
Cost: Minor

ATTIC/ROOF \ Hatch/Door
15. Condition: • [Not weatherstripped](#)
Implication(s): Chance of condensation damage to finishes and/or structure | Increased heating and cooling costs
Location: Ensuite Bathroom
Task: Improve
Time: Unpredictable
Cost: Minor



Description

Water supply source: • Public

Service piping into building: • [Copper](#)

Supply piping in building: • [Copper](#) • PEX (cross-linked Polyethylene)

Main water shut off valve at the: • South • Basement

Water flow and pressure: • [Functional](#)

Water heater type: • [Induced draft](#) • Rental

Water heater fuel/energy source: • [Gas](#)

Tank capacity: • [33.3 gallons](#)

Water heater approximate age: • 3 years

Water heater failure probability: • [Low](#)

Waste and vent piping in building: • [ABS plastic](#) • [Cast Iron](#)

Floor drain location: • Not visible.

Backwater valve: • Not visible

Limitations

Items excluded from a building inspection: • Concealed plumbing

Recommendations

WASTE PLUMBING \ Floor drain

16. Condition: • Not visible

Implication(s): Chance of water damage to contents, finishes and/or structure

Location: Basement

Task: Further evaluation

Description

Major floor finishes: • [Hardwood](#) • [Laminate](#)
Major wall finishes: • [Plaster/drywall](#)
Major ceiling finishes: • [Plaster/drywall](#)
Windows: • [Fixed](#) • [Single/double hung](#) • [Casement](#)
Glazing: • [Double](#)
Exterior doors - type/material: • Hinged • [Metal](#)
Party walls: • [Masonry](#)
Evidence of basement leakage: • None

Limitations

Inspection limited/prevented by: • New finishes/paint
Not included as part of a building inspection: • Appliances
Percent of foundation not visible: • 90 %

Recommendations

RECOMMENDATIONS \ Overview

17. **Condition:** • No interior recommendations are offered as a result of this inspection.

END OF REPORT

The links below connect you to a series of documents that will help you understand your home and how it works. These are in addition to links attached to specific items in the report.

Click on any link to read about that system.

» 01. ROOFING, FLASHINGS AND CHIMNEYS

» 02. EXTERIOR

» 03. STRUCTURE

» 04. ELECTRICAL

» 05. HEATING

» 06. COOLING/HEAT PUMPS

» 07. INSULATION

» 08. PLUMBING

» 09. INTERIOR

» 10. APPLIANCES

» 11. LIFE CYCLES AND COSTS

» 12. SUPPLEMENTARY

Asbestos

Radon

Urea Formaldehyde Foam Insulation (UFFI)

Lead

Carbon Monoxide

Mold

Household Pests

Termites and Carpenter Ants

» 13. HOME SET-UP AND MAINTENANCE

» 14. MORE ABOUT HOME INSPECTIONS