



# Your Inspection Report

2 O'Hara Place  
Toronto, ON M6K 1L9

**PREPARED FOR:**

KIM KEHOE  
LISTING AGENT

**INSPECTION DATE:**

Monday, April 7, 2025

**PREPARED BY:**

Scott Aitken

Aitken Home Inspections  
49 Riverdale Ave  
TORONTO, ON M4K 1C2

4164074663  
scottaitken@live.ca

April 7, 2025

Dear Kim Kehoe and Listing Agent,

RE: Report No. 4227  
2 O'Hara Place  
Toronto, ON  
M6K 1L9

Thanks very much for choosing us to perform your home inspection. The inspection itself and the attached report comply with the requirements of the Standards of Practice of our national Association. This document defines the scope of a home inspection.

Clients sometimes assume that a home inspection will include many things that are beyond the scope. We encourage you to read the Standards of Practice so that you clearly understand what things are included in the home inspection and report.

The report has been prepared for the exclusive use of our client. No use by third parties is intended. We will not be responsible to any parties for the contents of the report, other than the party named herein .

The report is effectively a snapshot of the house, recording the conditions on a given date and time. Home inspectors cannot predict future behavior, and as such, we cannot be responsible for things that occur after the inspection. If conditions change, we are available to revisit the property and update our report.

The report itself is copyrighted, and may not be used in whole or in part without our express written permission.

Again, thanks very much for choosing us to perform your home inspection.

Sincerely,

Scott Aitken  
on behalf of  
Aitken Home Inspections

Aitken Home Inspections  
49 Riverdale Ave  
TORONTO, ON M4K 1C2  
4164074663

scottaitken@live.ca

# AGREEMENT

Report No. 4227

2 O'Hara Place, Toronto, ON April 7, 2025

## PARTIES TO THE AGREEMENT

### Company

Aitken Home Inspections  
49 Riverdale Ave  
TORONTO, ON M4K 1C2

### Client

Kim Kehoe

### Client

Listing Agent

This is an agreement between Kim Kehoe, Listing Agent and Aitken Home Inspections.

THIS CONTRACT LIMITS THE LIABILITY OF THE HOME INSPECTION COMPANY.  
PLEASE READ CAREFULLY BEFORE SIGNING.

In addition to the limitations in the Standards of Practice, the Inspection of this property is subject to the Limitations and Conditions set out in this Agreement. The Inspection is performed in accordance with the Standards of Practice of our national association.

## LIMITATIONS AND CONDITIONS OF THE HOME INSPECTION

There are limitations to the scope of this Inspection. It provides a general overview of the more obvious repairs that may be needed. It is not intended to be an exhaustive list. The ultimate decision of what to repair or replace is yours. One homeowner may decide that certain conditions require repair or replacement, while another will not.

### 1) THE INSPECTION IS NOT TECHNICALLY EXHAUSTIVE.

The Home Inspection provides you with a basic overview of the condition of the property. Because your Home Inspector has only a limited amount of time to go through the property, the Inspection is not technically exhaustive.

Some conditions noted, such as foundation cracks or other signs of settling in a house, may either be cosmetic or may indicate a potential problem that is beyond the scope of the Home Inspection.

If you are concerned about any conditions noted in the Home Inspection Report, we strongly recommend that you consult a qualified Licensed Contractor or Consulting Engineer. These professionals can provide a more detailed analysis of any conditions noted in the Report at an additional cost

### 2) THE INSPECTION IS AN OPINION OF THE PRESENT CONDITION OF THE VISIBLE COMPONENTS.

The Home Inspector's Report is an opinion of the present condition of the property. It is based on a visual examination of the readily accessible features of the building.

A Home Inspection does not include identifying defects that are hidden behind walls, floors or ceilings. This includes wiring, heating, cooling, structure, plumbing and insulation that are hidden or inaccessible.

Some intermittent problems may not be obvious on a Home Inspection because they only happen under certain circumstances. As an example, your Home Inspector may not discover leaks that occur only during certain weather conditions or when a specific tap or appliance is being used in everyday life.

# AGREEMENT

2 O'Hara Place, Toronto, ON April 7, 2025

Report No. 4227

Home Inspectors will not find conditions that may only be visible when storage or furniture is moved. They do not remove wall coverings (including wallpaper) or lift flooring (including carpet) or move storage to look underneath or behind.

### 3) THE INSPECTION DOES NOT INCLUDE HAZARDOUS MATERIALS.

This includes building materials that are now suspected of posing a risk to health such as phenol-formaldehyde and urea-formaldehyde based insulation, fiberglass insulation and vermiculite insulation. The Inspector does not identify asbestos roofing, siding, wall, ceiling or floor finishes, insulation or fireproofing. We do not look for lead or other toxic metals in such things as pipes, paint or window coverings.

The Inspection does not deal with environmental hazards such as the past use of insecticides, fungicides, herbicides or pesticides. The Home Inspector does not look for, or comment on, the past use of chemical termite treatments in or around the property.

### 4) WE DO NOT COMMENT ON THE QUALITY OF AIR IN A BUILDING.

The Inspector does not try to determine if there are irritants, pollutants, contaminants, or toxic materials in or around the building.

The Inspection does not include spores, fungus, mold or mildew that may be present. You should note that whenever there is water damage noted in the report, there is a possibility that mold or mildew may be present, unseen behind a wall, floor or ceiling.

If anyone in your home suffers from allergies or heightened sensitivity to quality of air, we strongly recommend that you consult a qualified Environmental Consultant who can test for toxic materials, mold and allergens at additional cost.

### 5) WE DON'T LOOK FOR BURIED TANKS.

Your Home Inspector does not look for and is not responsible for fuel oil, septic or gasoline tanks that may be buried on the property. If the building had its heating system converted from oil, there will always be the possibility that a tank may remain buried on the property.

If fuel oil or other storage tanks remain on the property, you may be responsible for their removal and the safe disposal of any contaminated soil. If you suspect there is a buried tank, we strongly recommend that you retain a qualified Environmental Consultant to determine whether this is a potential problem.

### 6) TIME TO INVESTIGATE

We will have no liability for any claim or complaint if conditions have been disturbed, altered, repaired, replaced or otherwise changed before we have had a reasonable period of time to investigate.

### 7) REPORT IS FOR OUR CLIENT ONLY

The inspection report is for the exclusive use of the client named herein. No use of the information by any other party is intended.

# AGREEMENT

2 O'Hara Place, Toronto, ON April 7, 2025

Report No. 4227

## 8) CANCELLATION FEE

If the inspection is cancelled within 24 hours of the appointment time, a cancellation fee of 50% of the inspection fee will apply.

## 9) NOT A GUARANTEE, WARRANTY OR INSURANCE POLICY.

The inspection is not a guarantee, warranty or an insurance policy with regard to the fitness of the property.

## 10) LIMIT OF LIABILITY / LIQUIDATED DAMAGES

The liability of the Home Inspector and the Home Inspection Company arising out of this Inspection and Report, for any cause of action whatsoever, whether in contract or in negligence, is limited to a refund of the fees that you have been charged for this inspection.

**I, Kim Kehoe (Signature) \_\_\_\_\_, (Date) \_\_\_\_\_, have read, understood and accepted the terms of this agreement.**

**I, Listing Agent (Signature) \_\_\_\_\_, (Date) \_\_\_\_\_, have read, understood and accepted the terms of this agreement.**

# SUMMARY

Report No. 4227

2 O'Hara Place, Toronto, ON April 7, 2025

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

REFERENCE

Home in good overall condition.

This Summary outlines potentially significant issues from a cost or safety standpoint. This section is provided as a courtesy and cannot be considered a substitute for reading the entire report. Please read the complete document.

[Priority Maintenance Items](#)

This concludes the Summary section.

The remainder of the report describes each of the home's systems and also details any recommendations we have for improvements. Limitations that restricted our inspection are included as well.

The suggested time frames for completing recommendations are based on the limited information available during a pre-purchase home inspection. These may have to be adjusted based on the findings of specialists.

[Home Improvement - ballpark costs](#)

# ROOFING

Report No. 4227

2 O'Hara Place, Toronto, ON April 7, 2025

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

REFERENCE

## Description

The home is considered to face: • East

Sloped roofing material:

- [Asphalt shingles](#)



1.

Flat roofing material:

- [Modified bitumen membrane](#)



2.

Probability of leakage: • Low

Approximate age: • 10-15 years

# ROOFING

Report No. 4227

2 O'Hara Place, Toronto, ON April 7, 2025

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

REFERENCE

## Limitations

**Inspection performed:** • From roof edge

## Recommendations

### **RECOMMENDATIONS \ General**

**1. Condition:** • Cut branches back from roof.

**Location:** West Exterior

**Task:** Remove

**Time:** Regular maintenance

**Cost:** Minor



# EXTERIOR

Report No. 4227

2 O'Hara Place, Toronto, ON April 7, 2025

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

REFERENCE

## Description

Gutter & downspout material: • [Aluminum](#)

Downspout discharge: • [Above grade](#)

Lot slope: • [Flat](#)

Soffit (underside of eaves) and fascia (front edge of eaves): • [Wood](#) • [Aluminum](#)

Wall surfaces and trim: • [Metal siding](#) • [Brick](#)

Driveway: • Asphalt

Deck: • Ground level • Pressure-treated wood

Porch: • Wood

## Limitations

No or limited access to:

- Area below steps, deck, porches
  - North wall
- At addition.

## Recommendations

### ROOF DRAINAGE \ Gutters

2. Condition: • [Clogged](#)

Implication(s): Chance of water damage to structure, finishes and contents

Task: Clean

Time: Regular maintenance

Cost: Minor

### WALLS \ Masonry (brick, stone) and concrete

3. Condition: • [Parging damaged or missing](#)

Implication(s): Chance of damage to structure | Shortened life expectancy of material

Location: South Exterior

Task: Repair

Time: Regular maintenance

Cost: Minor

# EXTERIOR

Report No. 4227

2 O'Hara Place, Toronto, ON April 7, 2025

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

REFERENCE




3.

**4. Condition:** • Some prior brick repairs evident at brick veneer. Periodic repair may be required due to age of brick, not urgent.

**Location:** South Exterior

**Task:** Monitor



4.

## LANDSCAPING \ Driveway

**5. Condition:** • [Improper slope or drainage](#)

Add or remove asphalt to create drainage slope away from foundation.

# EXTERIOR

Report No. 4227

2 O'Hara Place, Toronto, ON April 7, 2025

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

REFERENCE

**Implication(s):** Chance of water damage to structure, finishes and contents


**Location:** South Exterior

**Task:** Repair

**Time:** Unpredictable

**Cost:** Minor

**Walk/patio sloping towards house**



# EXTERIOR

Report No. 4227

2 O'Hara Place, Toronto, ON April 7, 2025

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

REFERENCE



5.

# STRUCTURE

Report No. 4227

2 O'Hara Place, Toronto, ON April 7, 2025

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

REFERENCE

## Description

**Configuration:** • [Basement](#) • [Crawlspace](#)

**Foundation material:**

• [Stone](#)

• [Brick](#)

• Not visible

At crawlspace.

**Floor construction:** • [Joists](#) • Subfloor - plank

**Exterior wall construction:** • [Wood frame](#) • [Wood frame / Brick veneer](#)

**Roof and ceiling framing:** • Rafters • Not visible

**Party wall:** • [Wood frame](#)

## Limitations

**Attic/roof space:** • No access

**Percent of foundation not visible:** • 75 %

## Recommendations

### FOUNDATIONS \ Performance opinion

**6. Condition:** • Not determined

Recommend creating access to crawl space to inspect structure. Hatch present but sealed.

**Location:** Crawl Space

**Task:** Further evaluation

## Description

**Service entrance cable and location:** • [Overhead copper](#)

**Service size:** • [100 Amps \(240 Volts\)](#)

**Main disconnect/service box rating:** • [100 Amps](#)

**Main disconnect/service box type and location:** • [Breakers - basement](#)

**System grounding material and type:** • [Copper - water pipe](#)

**Distribution panel type and location:** • [Breakers - basement](#)

**Distribution panel rating:** • [100 Amps](#)

**Distribution wire (conductor) material and type:** • [Copper - non-metallic sheathed](#)

**Type and number of outlets (receptacles):** • [Grounded - minimal](#)

**Circuit interrupters: Ground Fault (GFCI) & Arc Fault (AFCI):** • No AFCI • Gfci's in some areas only.

## Limitations

**Not included as part of a building inspection:** • Concealed Wiring

## Recommendations

### SERVICE BOX, GROUNDING AND PANEL \ Distribution fuses/breakers

**7. Condition:** • [Double taps](#)

Add breaker and split double tap if nuisance tripping occurs.

**Implication(s):** Fire hazard



**Location:** Basement Panel

**Task:** Improve

**Time:** Unpredictable

**Cost:** Minor

## Double tapping (double lugging)



6.

### DISTRIBUTION SYSTEM \ Outlets (receptacles)

8. Condition: • [GFCI/GFI needed \(Ground Fault Circuit Interrupter\)](#)


Implication(s): Electric shock

Location: Kitchen

Task: Replace

Time: Immediate



**Cost:** Minor

7.

**DISTRIBUTION SYSTEM \ Outlets (receptacles) - number or location****9. Condition:** • [Too few outlets](#)

Add outlets to eliminate use of extension cords.

**Implication(s):** Nuisance**Location:** Second Floor**Task:** Improve**Cost:** \$400 - \$500 each



**10. Condition:** • Poor location

Raise cabinet or relocate outlet to allow access to reset.

**Location:** Second Floor Bathroom

**Task:** Repair

**Time:** Immediate

**Cost:** Minor



8.

**DISTRIBUTION SYSTEM \ Switches****11. Condition:** • Poor location of switches.

Relocate upper stair and bedroom switches.

**Location:** Second Floor

**Task:** Improve

**Time:** Immediate

**Cost:** Minor



9.

**DISTRIBUTION SYSTEM \ Lights****12. Condition:** • [Inoperative](#)**Implication(s):** Inadequate lighting**Location:** Bedroom**Task:** Repair**Cost:** Minor**13. Condition:** • [Loose](#)**Implication(s):** Electric shock | Fire hazard**Location:** First Floor Closet**Task:** Repair**Time:** Immediate**Cost:** Minor

# ELECTRICAL

Report No. 4227

2 O'Hara Place, Toronto, ON April 7, 2025

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

REFERENCE



10.

# HEATING

Report No. 4227

2 O'Hara Place, Toronto, ON April 7, 2025

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

REFERENCE

## Description

**Heating system type:** • [Furnace](#)

**Fuel/energy source:** • [Gas](#)

**Heat distribution:** • [Ducts and registers](#)

**Approximate capacity:** • 40,000 BTU/hr

**Efficiency:** • [High-efficiency](#)

**Combustion air source:** • Outside

**Approximate age:** • [5 years](#)

**Main fuel shut off at:** • Meter

**Failure probability:** • [Low](#)

**Air filter:** • Disposable

**Chimney/vent:**

- [Metal](#)

For water heater only.

- High temperature plastic

For furnace only.

- Sidewall venting

For furnace only.

**Humidifier:** • Not present

**Condensate system:** • Electric pump

## Limitations

**Heat loss calculations:** • Not done as part of a building inspection

## Recommendations

### FURNACE \ Ducts, registers and grilles

**14. Condition:** • Missing

Add heat to second floor washroom to protect plumbing, leave door open until heat is added.

**Implication(s):** Increased heating costs | Reduced comfort

**Location:** Second Floor Bathroom

**Task:** Provide

**Time:** Before next heating season

**Cost:** Depends on approach

# COOLING & HEAT PUMP

Report No. 4227

2 O'Hara Place, Toronto, ON April 7, 2025

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

REFERENCE

## Description

**Air conditioning type:** • [Air cooled](#) • Central

**Cooling capacity:** • [18,000 BTU/hr](#)

**Compressor approximate age:** • 5 years

**Failure probability:** • [Low](#)

## Limitations

**Inspection limited/prevented by:**

- Low outdoor temperature
- System not tested, test before cooling season.

## Recommendations

**AIR CONDITIONING \ Air cooled condenser coil**

**15. Condition:** • [Dirty](#)

**Implication(s):** Reduced system life expectancy | Increased cooling costs | Reduced comfort


**Location:** South Exterior

**Task:** Clean

**Time:** Regular maintenance

**Cost:** Minor

## Inspecting the condenser unit



11.

# INSULATION AND VENTILATION

Report No. 4227

2 O'Hara Place, Toronto, ON April 7, 2025

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

REFERENCE

## Description

**Attic/roof insulation material:** • Not determined

**Attic/roof insulation amount/value:** • Not determined

**Attic/roof ventilation:** • [Roof vent](#)

**Wall insulation material:** • [Glass fiber](#)

**Wall insulation amount/value:** • Spot checked only • 0-12

**Foundation wall insulation material:** • Not visible

## Limitations

**Inspection limited/prevented by lack of access to:** • Attic • Crawlspace

## Recommendations

### RECOMMENDATIONS \ Overview

**16. Condition:** • Increased insulation is an improvement and not an essential repair.

## Description

**Water supply source (based on observed evidence):** • Public

**Service piping into building:** • [Not visible](#)

**Supply piping in building:** • [Copper](#)

**Main water shut off valve at the:**

- North
- East
- Basement



12.

**Water flow and pressure:** • [Typical for neighborhood](#)

**Water heater type:** • [Conventional](#) • Tank • Rental

**Water heater fuel/energy source:** • [Gas](#)

**Water heater tank capacity:** • [40 gallons](#)

**Water heater approximate age:** • 18 years

**Water heater failure probability:** • [High](#)

**Waste and vent piping in building:** • [ABS plastic](#) • [Cast iron](#)

**Pumps:** • No sump present

**Floor drain location:** • Front of basement.

**Backwater valve:** • Not present



## Limitations

**Items excluded from a building inspection:** • Concealed plumbing

## Recommendations

### WATER HEATER \ Life expectancy

**17. Condition:** • [Near end of life expectancy](#)

Replace with direct vent type to allow for eventual chimney removal.

**Implication(s):** No hot water

**Location:** Basement

**Task:** Replace

**Time:** Unpredictable

**Cost:** Rental

### WATER HEATER - GAS BURNER AND VENTING \ Venting system

**18. Condition:** • Replace missing cap at top of metal chimney, reseal metal flashing. This chimney can be removed at reshingling in future if water heater is replaced with direct vent type.

**Location:** Southwest

**Task:** Repair

**Time:** Unpredictable

**Cost:** Minor



13.

# INTERIOR

Report No. 4227

2 O'Hara Place, Toronto, ON April 7, 2025

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

REFERENCE

## Description

Major floor finishes: • [Hardwood](#) • [Ceramic](#) • [Softwood](#)

Major wall finishes: • [Plaster/drywall](#)

Major ceiling finishes: • [Plaster/drywall](#)

Windows: • [Sliders](#) • [Casement](#) • [Awning](#)

Glazing: • [Double](#)

Exterior doors - type/material: • Hinged • [Sliding glass](#) • Metal-clad

Party wall: • [Wood frame](#)

## Limitations

Inspection limited/prevented by: • Storage/furnishings

Not included as part of a building inspection: • Appliances

Percent of foundation not visible: • 75 %

## Recommendations

### RECOMMENDATIONS \ Overview

19. Condition: • Typical minor cosmetic flaws present.

### WALLS \ Masonry or concrete

20. Condition: • Fill and parge exposed masonry as needed.

Location: Basement

Task: Repair

Time: Regular maintenance

Cost: Minor

# INTERIOR

Report No. 4227

2 O'Hara Place, Toronto, ON April 7, 2025

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

REFERENCE



14.

## DOORS \ General notes

**21. Condition:** • Needs adjustment.  
Adjust south sliding door.

**Location:** First Floor Living Room

**Task:** Repair

**Time:** Before use

**Cost:** Minor

# INTERIOR

Report No. 4227

2 O'Hara Place, Toronto, ON April 7, 2025

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

REFERENCE



15.

## **STAIRS \ General notes**

**22. Condition:** • Very steep.

Recommend improving existing guardrail at second floor stairs, adding guardrail improving handrail at basement stairs.

**Location:** Staircases

**Task:** Improve

**Time:** Immediate

**Cost:** Depends on approach

# INTERIOR

Report No. 4227

2 O'Hara Place, Toronto, ON April 7, 2025

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

REFERENCE



16.



17.

## EXHAUST FANS \ General notes

23. Condition: • [Noisy](#)

**Implication(s):** Reduced system life expectancy | Equipment failure

**Location:** Second Floor Bathroom

**Task:** Replace

**Time:** Unpredictable

**Cost:** Minor

**END OF REPORT**

# REFERENCE LIBRARY

2 O'Hara Place, Toronto, ON April 7, 2025

Report No. 4227

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

## REFERENCE

The links below connect you to a series of documents that will help you understand your home and how it works. These are in addition to links attached to specific items in the report.

Click on any link to read about that system.

» 01. ROOFING, FLASHINGS AND CHIMNEYS

» 02. EXTERIOR

» 03. STRUCTURE

» 04. ELECTRICAL

» 05. HEATING

» 06. COOLING/HEAT PUMPS

» 07. INSULATION

» 08. PLUMBING

» 09. INTERIOR

» 10. APPLIANCES

» 11. LIFE CYCLES AND COSTS

» 12. SUPPLEMENTARY

Asbestos

Radon

Urea Formaldehyde Foam Insulation (UFFI)

Lead

Carbon Monoxide

Mold

Household Pests

Termites and Carpenter Ants

» 13. HOME SET-UP AND MAINTENANCE

» 14. MORE ABOUT HOME INSPECTIONS