



Your Inspection Report

189 Argyle Street
Toronto, ON M6J 1P5

PREPARED FOR:

KIM KEHOE
LISTING AGENT

INSPECTION DATE:

Thursday, May 15, 2025

PREPARED BY:

Scott Aitken

Aitken Home Inspections
49 Riverdale Ave
TORONTO, ON M4K 1C2

4164074663
scottaitken@live.ca

May 15, 2025

Dear Kim Kehoe and Listing Agent,

RE: Report No. 4273
189 Argyle Street
Toronto, ON
M6J 1P5

Thanks very much for choosing us to perform your home inspection. The inspection itself and the attached report comply with the requirements of the Standards of Practice of our national Association. This document defines the scope of a home inspection.

Clients sometimes assume that a home inspection will include many things that are beyond the scope. We encourage you to read the Standards of Practice so that you clearly understand what things are included in the home inspection and report.

The report has been prepared for the exclusive use of our client. No use by third parties is intended. We will not be responsible to any parties for the contents of the report, other than the party named herein .

The report is effectively a snapshot of the house, recording the conditions on a given date and time. Home inspectors cannot predict future behavior, and as such, we cannot be responsible for things that occur after the inspection. If conditions change, we are available to revisit the property and update our report.

The report itself is copyrighted, and may not be used in whole or in part without our express written permission.

Again, thanks very much for choosing us to perform your home inspection.

Sincerely,

Scott Aitken
on behalf of
Aitken Home Inspections

Aitken Home Inspections
49 Riverdale Ave
TORONTO, ON M4K 1C2
4164074663

scottaitken@live.ca

AGREEMENT

Report No. 4273

189 Argyle Street, Toronto, ON May 15, 2025

PARTIES TO THE AGREEMENT

Company

Aitken Home Inspections
49 Riverdale Ave
TORONTO, ON M4K 1C2

Client

Kim Kehoe

Client

Listing Agent

This is an agreement between Kim Kehoe, Listing Agent and Aitken Home Inspections.

THIS CONTRACT LIMITS THE LIABILITY OF THE HOME INSPECTION COMPANY.
PLEASE READ CAREFULLY BEFORE SIGNING.

In addition to the limitations in the Standards of Practice, the Inspection of this property is subject to the Limitations and Conditions set out in this Agreement. The Inspection is performed in accordance with the Standards of Practice of our national association.

LIMITATIONS AND CONDITIONS OF THE HOME INSPECTION

There are limitations to the scope of this Inspection. It provides a general overview of the more obvious repairs that may be needed. It is not intended to be an exhaustive list. The ultimate decision of what to repair or replace is yours. One homeowner may decide that certain conditions require repair or replacement, while another will not.

1) THE INSPECTION IS NOT TECHNICALLY EXHAUSTIVE.

The Home Inspection provides you with a basic overview of the condition of the property. Because your Home Inspector has only a limited amount of time to go through the property, the Inspection is not technically exhaustive.

Some conditions noted, such as foundation cracks or other signs of settling in a house, may either be cosmetic or may indicate a potential problem that is beyond the scope of the Home Inspection.

If you are concerned about any conditions noted in the Home Inspection Report, we strongly recommend that you consult a qualified Licensed Contractor or Consulting Engineer. These professionals can provide a more detailed analysis of any conditions noted in the Report at an additional cost

2) THE INSPECTION IS AN OPINION OF THE PRESENT CONDITION OF THE VISIBLE COMPONENTS.

The Home Inspector's Report is an opinion of the present condition of the property. It is based on a visual examination of the readily accessible features of the building.

A Home Inspection does not include identifying defects that are hidden behind walls, floors or ceilings. This includes wiring, heating, cooling, structure, plumbing and insulation that are hidden or inaccessible.

Some intermittent problems may not be obvious on a Home Inspection because they only happen under certain circumstances. As an example, your Home Inspector may not discover leaks that occur only during certain weather conditions or when a specific tap or appliance is being used in everyday life.

AGREEMENT

189 Argyle Street, Toronto, ON May 15, 2025

Report No. 4273

Home Inspectors will not find conditions that may only be visible when storage or furniture is moved. They do not remove wall coverings (including wallpaper) or lift flooring (including carpet) or move storage to look underneath or behind.

3) THE INSPECTION DOES NOT INCLUDE HAZARDOUS MATERIALS.

This includes building materials that are now suspected of posing a risk to health such as phenol-formaldehyde and urea-formaldehyde based insulation, fiberglass insulation and vermiculite insulation. The Inspector does not identify asbestos roofing, siding, wall, ceiling or floor finishes, insulation or fireproofing. We do not look for lead or other toxic metals in such things as pipes, paint or window coverings.

The Inspection does not deal with environmental hazards such as the past use of insecticides, fungicides, herbicides or pesticides. The Home Inspector does not look for, or comment on, the past use of chemical termite treatments in or around the property.

4) WE DO NOT COMMENT ON THE QUALITY OF AIR IN A BUILDING.

The Inspector does not try to determine if there are irritants, pollutants, contaminants, or toxic materials in or around the building.

The Inspection does not include spores, fungus, mold or mildew that may be present. You should note that whenever there is water damage noted in the report, there is a possibility that mold or mildew may be present, unseen behind a wall, floor or ceiling.

If anyone in your home suffers from allergies or heightened sensitivity to quality of air, we strongly recommend that you consult a qualified Environmental Consultant who can test for toxic materials, mold and allergens at additional cost.

5) WE DON'T LOOK FOR BURIED TANKS.

Your Home Inspector does not look for and is not responsible for fuel oil, septic or gasoline tanks that may be buried on the property. If the building had its heating system converted from oil, there will always be the possibility that a tank may remain buried on the property.

If fuel oil or other storage tanks remain on the property, you may be responsible for their removal and the safe disposal of any contaminated soil. If you suspect there is a buried tank, we strongly recommend that you retain a qualified Environmental Consultant to determine whether this is a potential problem.

6) TIME TO INVESTIGATE

We will have no liability for any claim or complaint if conditions have been disturbed, altered, repaired, replaced or otherwise changed before we have had a reasonable period of time to investigate.

7) REPORT IS FOR OUR CLIENT ONLY

The inspection report is for the exclusive use of the client named herein. No use of the information by any other party is intended.

AGREEMENT

189 Argyle Street, Toronto, ON May 15, 2025

Report No. 4273

8) CANCELLATION FEE

If the inspection is cancelled within 24 hours of the appointment time, a cancellation fee of 50% of the inspection fee will apply.

9) NOT A GUARANTEE, WARRANTY OR INSURANCE POLICY.

The inspection is not a guarantee, warranty or an insurance policy with regard to the fitness of the property.

10) LIMIT OF LIABILITY / LIQUIDATED DAMAGES

The liability of the Home Inspector and the Home Inspection Company arising out of this Inspection and Report, for any cause of action whatsoever, whether in contract or in negligence, is limited to a refund of the fees that you have been charged for this inspection.

I, Kim Kehoe (Signature)_____ , (Date)_____, have read, understood and accepted the terms of this agreement.

I, Listing Agent (Signature)_____ , (Date)_____, have read, understood and accepted the terms of this agreement.

SUMMARY

189 Argyle Street, Toronto, ON May 15, 2025

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

REFERENCE

This Summary outlines potentially significant issues from a cost or safety standpoint. This section is provided as a courtesy and cannot be considered a substitute for reading the entire report. Please read the complete document.

[Priority Maintenance Items](#)

Exterior

WALLS \ Flashings and caulking

Condition: • [Flashings missing](#)

Kickout flashing missing at base of metal siding on west wall.

Joints at hardboard siding lack flashings leaving secondary membrane exposed and vulnerable to damage (typically from sunlight).

Implication(s): Chance of water damage to structure, finishes and contents

Location: Various Exterior

Task: Improve

Time: Unpredictable

Cost: Consult Contractor For Cost

Cooling & Heat Pump

AIR CONDITIONING \ General notes

Condition: • Service air conditioner

A/C short cycles and does not run. Service needed.

Implication(s): Reduced system life expectancy | Increased cooling costs | Reduced comfort

Task: Repair

Time: Before use

Cost: De

This concludes the Summary section.

The remainder of the report describes each of the home's systems and also details any recommendations we have for improvements. Limitations that restricted our inspection are included as well.

The suggested time frames for completing recommendations are based on the limited information available during a pre-purchase home inspection. These may have to be adjusted based on the findings of specialists.

[Home Improvement - ballpark costs](#)

ROOFING

Report No. 4273

189 Argyle Street, Toronto, ON May 15, 2025

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR


REFERENCE

Description

The home is considered to face: • North

Flat roofing material:


- [Modified bitumen membrane](#)



1.



2.



3.



4.

ROOFING

Report No. 4273

189 Argyle Street, Toronto, ON May 15, 2025

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

REFERENCE

Probability of leakage: • Low

Approximate age:

• 10 years

At garage

• 12 years

At house

Limitations

Inspection limited/prevented by: • Deck, could not inspect roof membrane below.

Inspection performed: • By walking on roof

Recommendations

RECOMMENDATIONS \ Overview

1. Condition: • No roofing recommendations are offered as a result of this inspection.

All visible areas in good condition.

EXTERIOR

Report No. 4273

189 Argyle Street, Toronto, ON May 15, 2025

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

REFERENCE

Description

Gutter & downspout material: • [Aluminum](#)

Downspout discharge: • [Above grade](#)

Lot slope: • [Flat](#)

Wall surfaces and trim: • [Metal siding](#) • [Brick](#) • [Wood](#) • [Hardboard](#)

Retaining wall: • [Masonry](#)

Walkway: • Concrete

Deck: • Pressure-treated wood

Porch: • Concrete

Balcony: • Synthetic wood • Glass railings • Modified bitumen.

Patio: • Pavers

Garage: • Detached • Masonry

Limitations

Inspection limited/prevented by: • Storage in garage

Recommendations

WALLS \ Flashings and caulking

2. Condition: • [Flashings missing](#)

Kickout flashing missing at base of metal siding on west wall.

Joints at hardboard siding lack flashings leaving secondary membrane exposed and vulnerable to damage (typically from sunlight).

Implication(s): Chance of water damage to structure, finishes and contents

Location: Various Exterior

Task: Improve

Time: Unpredictable

Cost: Consult Contractor For Cost

EXTERIOR

Report No. 4273

189 Argyle Street, Toronto, ON May 15, 2025

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING


COOLING

INSULATION

PLUMBING

INTERIOR

REFERENCE



5.



6.

WALLS \ Wood siding

3. Condition: • [Paint or stain - needed](#)

Wood siding due for paint maintenance.

Implication(s): Shortened life expectancy of material

Location: Various Exterior

Task: Improve

Time: Regular maintenance

Cost: Minor

LANDSCAPING \ Walkway

4. Condition: • Poor drainage and downspout terminations at both n/e and n/w walkways is contributing to leakage and cracking at retaining wall.

Location: North Exterior

Task: Improve

Time: Unpredictable

Cost: Minor

EXTERIOR

189 Argyle Street, Toronto, ON May 15, 2025

Report No. 4273

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING



COOLING

INSULATION

PLUMBING

INTERIOR

REFERENCE



7.



8.

LANDSCAPING \ Patios

5. Condition: • Improper slope or drainage

EXTERIOR

Report No. 4273

189 Argyle Street, Toronto, ON May 15, 2025

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

REFERENCE

Lift and relay interlocking to create drainage away from foundation.

Implication(s): Chance of water damage to structure, finishes and contents

Location: South Exterior

Task: Improve

Time: Unpredictable

Cost: Minor



9.

STRUCTURE

Report No. 4273

189 Argyle Street, Toronto, ON May 15, 2025

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

REFERENCE

Description

Configuration: • [Basement](#)

Foundation material: • [Poured concrete](#) • [Masonry block](#)

Floor construction: • [Wood I-joists](#) • Subfloor - plywood

Exterior wall construction:

• Not visible

Likely wood frame.

Roof and ceiling framing: • Roof Joists • Not visible

Limitations

Attic/roof space:

• No access

Typical for flat roof.

Percent of foundation not visible: • 99 %

Recommendations

RECOMMENDATIONS \ Overview

6. Condition: • No structure recommendations are offered as a result of this inspection.

7. Condition: • All visible structural members in good condition.

Description

Service entrance cable and location: • [Overhead copper](#)

Service size: • [200 Amps \(240 Volts\)](#)

Main disconnect/service box rating: • [200 Amps](#)

Main disconnect/service box type and location: • [Breakers - basement](#)

System grounding material and type: • [Copper - water pipe](#)

Distribution panel type and location: • [Breakers - basement](#)

Distribution panel rating: • [200 Amps](#)

Auxiliary panel (subpanel) type and location: • [Breakers - garage](#)

Distribution wire (conductor) material and type: • [Copper - non-metallic sheathed](#)

Type and number of outlets (receptacles): • [Grounded - typical](#)

Circuit interrupters: Ground Fault (GFCI) & Arc Fault (AFCI): • [GFCIs present](#) • [AFCIs present](#)

Smoke alarms (detectors): • [Present](#)

Limitations

Not included as part of a building inspection: • Concealed Wiring

Recommendations

RECOMMENDATIONS \ Overview

8. Condition: • No electrical recommendations are offered as a result of this inspection.

All visible electrical in good condition.

HEATING

Report No. 4273

189 Argyle Street, Toronto, ON May 15, 2025

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

REFERENCE

Description

Heating system type: • [Furnace](#)

Fuel/energy source: • [Gas](#)

Heat distribution: • [Ducts and registers](#)

Approximate capacity: • [80,000 BTU/hr](#)

Efficiency: • [High-efficiency](#)

Combustion air source: • Outside

Approximate age: • [12 years](#)

Main fuel shut off at: • Meter

Failure probability: • [Low](#)

Air filter: • Disposable

Chimney/vent: • High temperature plastic • Sidewall venting

Humidifier: • None

Condensate system: • Discharges into floor drain

Limitations

Warm weather: • Prevents testing heating effectiveness

Heat loss calculations: • Not done as part of a building inspection

Recommendations

RECOMMENDATIONS \ Overview

9. Condition: • No heating recommendations are offered as a result of this inspection.

COOLING & HEAT PUMP

Report No. 4273

189 Argyle Street, Toronto, ON May 15, 2025

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

REFERENCE

Description

Air conditioning type: • [Air cooled](#) • Central

Cooling capacity: • [36,000 BTU/hr](#)

Compressor approximate age: • 3 years

Failure probability: • [Low](#)

Limitations

Heat gain calculations: • Not done as part of a building inspection

Recommendations

AIR CONDITIONING \ General notes

10. Condition: • Service air conditioner

A/C short cycles and does not run. Service needed.

Implication(s): Reduced system life expectancy | Increased cooling costs | Reduced comfort

Task: Repair

Time: Before use

Cost: De

INSULATION AND VENTILATION

Report No. 4273

189 Argyle Street, Toronto, ON May 15, 2025

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

REFERENCE

Description

Attic/roof insulation material: • Not determined

Attic/roof insulation amount/value: • Not determined

Wall insulation material: • Spray foam

Wall insulation amount/value: • [R-20](#) • Spot checked only

Foundation wall insulation material: • Spray foam.

Foundation wall insulation amount/value: • [R-20](#)

Limitations

Inspection limited/prevented by lack of access to: • Roof space

Recommendations

RECOMMENDATIONS \ Overview

11. Condition: • No insulation recommendations are offered as a result of this inspection.

Description

Water supply source (based on observed evidence): • Public

Service piping into building:

- [Copper](#)

3/4 inch

Supply piping in building: • PEX (cross-linked Polyethylene)

Main water shut off valve at the: • Furnace room

Water flow and pressure: • Good

Water heater type: • Tankless/On demand

Water heater fuel/energy source: • [Gas](#)

Water heater approximate age: • 11 years

Water heater failure probability: • [Low](#)

Waste and vent piping in building: • [ABS plastic](#)

Pumps:

- [Solid waste pump \(ejector pump\)](#)



10.

- [Sump pump](#)

PLUMBING

189 Argyle Street, Toronto, ON May 15, 2025

Report No. 4273

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

REFERENCE



11.

Floor drain location: • Near heating system

Backwater valve: • Not visible

Limitations

Items excluded from a building inspection: • Concealed plumbing

Recommendations

WASTE PLUMBING \ Sump pump

12. Condition: • Recommend installation of backup pump and power supply.

Location: Basement

Task: Install

Time: Unpredictable

Cost: \$1,500

INTERIOR

Report No. 4273

189 Argyle Street, Toronto, ON May 15, 2025

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

REFERENCE

Description

Major floor finishes: • Ceramic/porcelain • Engineered wood

Major wall finishes: • [Plaster/drywall](#)

Major ceiling finishes: • [Plaster/drywall](#)

Windows: • [Fixed](#) • [Awning](#) • [Skylight](#)

Glazing: • [Double](#)

Exterior doors - type/material: • Hinged • [Sliding glass](#) • [Metal](#) • Glass

Limitations

Inspection limited/prevented by: • Storage/furnishings

Not included as part of a building inspection: • Appliances

Percent of foundation not visible: • 99 %

Recommendations

RECOMMENDATIONS \ Overview

13. Condition: • Typical minor cosmetic flaws present.

END OF REPORT

REFERENCE LIBRARY

Report No. 4273

189 Argyle Street, Toronto, ON May 15, 2025

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

REFERENCE

The links below connect you to a series of documents that will help you understand your home and how it works. These are in addition to links attached to specific items in the report.

Click on any link to read about that system.

» 01. ROOFING, FLASHINGS AND CHIMNEYS

» 02. EXTERIOR

» 03. STRUCTURE

» 04. ELECTRICAL

» 05. HEATING

» 06. COOLING/HEAT PUMPS

» 07. INSULATION

» 08. PLUMBING

» 09. INTERIOR

» 10. APPLIANCES

» 11. LIFE CYCLES AND COSTS

» 12. SUPPLEMENTARY

Asbestos

Radon

Urea Formaldehyde Foam Insulation (UFFI)

Lead

Carbon Monoxide

Mold

Household Pests

Termites and Carpenter Ants

» 13. HOME SET-UP AND MAINTENANCE

» 14. MORE ABOUT HOME INSPECTIONS